

# ABSTRACT

A method for treating a surface to decontaminate the surface by chemically altering contaminants on the surface. The method comprises applying to the surface particles of  
5 a zero valent metal capable of reacting with oxygen and water to form hydroxyl radicals, and exposing the particles to oxygen and water. The method may be carried out in the presence of air.